EcoNet and Flash Codes

Inverter Product

The error codes below will be displayed at the EcoNet Control Center under Service window / Current Faults or in the Fault History and will be time & date stamped. VSODC (Variable Speed Outdoor Unit Control – EcoNet control board) fault code is what will be displayed on the VSODC

EcoNet error code at Control Center	VSODU Fault Code	Description	Possible Resolution(s)	EV2 Drive LED Code
A900_O Or A930_O Inverter Fault – Identity Fault	8	 The inverter drive itself is not programmed and is not field serviceable. This fault should not occur in the field. 	Return Drive to Distributor	
T901_O Inverter Fault – Compressor Overcurrent	15	Compressor is pulling more current than allowed in order to start	 System Grossly Overcharged Compressor full of liquid/oil Compressor Shorted to Ground – Check resistance of windings to ground. Tight Compressor 	Yellow 1 or 3 Flashes Or Red 4 Flashes
T902 Inverter Fault – Envelope Protection	∃ !	Compressor current outside of predetermined envelope for RPM's	 Will display 31 at VSODU at time of fault – Will return to operation after time delay Must occur 15 times in a 24 hour period to be displayed in control center fault history. Verify refrigerant charge, often related to overcharge or high condensing pressures. Flooded Start Verify Airflow 	
T903_O Inverter Fault – PFC Overcurrent	15	PFC (Power Factor Correction) module is detecting high current internally	Check Choke Connections – Replace Choke if it looks burnt. If Choke doesn't work, check drive	

EcoNet and Flash Codes

T905_O Inverter Fault – DC Bus Undervoltage	!5 b	DC Bus voltage has dropped below acceptable voltage DC Bus Voltage <175 VDC	 Incoming Voltage should be greater than 187 VAC. Fault will reset when voltage is returned. Early VSODU firmware (Before VSODU Rev 57) may not properly reset this fault. Update VSODU firmware to current revision. Can occur with power flicker due to storms, will reset when voltage returns after 5 minute delay. Check Incoming Line Voltage to Drive. Drive will reset after fault first two times. If unit locks out on third fault, it will reset in 30 minutes. Countdown timer on EcoNet will display "Locked" 	Yellow 8 Flashes
A906_O Inverter Fault – AC Input Overvoltage	28 .	ncoming Voltage >253 VAC	 Verify Incoming voltage to Drive by measuring voltage at L1 to L2 Contact Utility if voltage is greater than 253 VAC for a solution. 	Yellow 10 Flashes
A907_O Inverter Fault – AC Input Undervoltage	- I	ncoming voltage <187 VAC	 Verify Incoming voltage to Drive by measuring voltage at L1 to L2 on drive. Voltage must be <187 VAC. Could be caused by dirty power. 	Yellow 9 Flashes
T908_O Inverter Fault – PIM Over-temp	15	ndicates the Power Inverter Module on the drive is overheated. May stop compressor, or fold pack compressor RPM	 Check Outdoor fan operation Check Condenser coil for cleanliness Check Drive Heat Sink. Make sure unit clearances are correct. 	Yellow 4 or 18 Flashes

EcoNet and Flash Codes

T909_O Inverter Fault – PFC Over-temp	15	 Indicates the Power Factor Correction circuit is overheated. May stop or fold back compressor RPM 	 Check Outdoor fan operation Check Condenser coil for cleanliness Check Drive Heat Sink. Make sure unit clearances are correct. 	Yellow 5 or 19 Flashes
A910_O Inverter Fault – Lost Rotor Position	15	Compressor speed not matching speed command from control	 Verify Compressor Connections at U, V, W and Molded plug Verify order/wiring at U, V, W. Check for Equal Resistance on compressor windings System Grossly Overcharged Compressor Tight or Locked 	Yellow 2 Flashes
T911_O Inverter Fault – Current Imbalance	15	Compressor Current Imbalance	 Verify Compressor Connections at U, V, W and Molded plug Check Compressor Windings for significant differences in resistance as they should be equal. 	Red 14 Flashes
A912_O Inverter Fault – Micro Fault	15	Micro on Drive faulted	Hard Reset on Drive If Hard Reset fails, replace Drive	Red 13 Flashes
A913_O Inverter Fault - PIM Sensor Open	15	Power Inverter Module temperature sensor is open	Hard Reset on Drive If fault persists, Replace Drive	Red 2 Flashes
T914_O Inverter Fault – DC Voltage Low	15	• DC Bus Voltage is running low	 Check Incoming Line Voltage to drive at L1 to L2. Voltage on DC Bus is generally 300 to 380 VDC. Check choke connections. PIM on Drive Defective 	Yellow 17 Flashes

EcoNet and Flash Codes

T916_O Inverter Fault – Discharge Temp	15	Compressor Discharge Temperature has exceed 235°F degrees for 30 seconds, and compressor may fold back until temperature is below 200°F	 Verify Operating Superheat and Charge Check Reversing Valve for leakage from Discharge to Suction Check DLT Sensor Connection to Drive Verify DLT sensor resistance Should trip on T961_O first. 	Yellow 6 Flashes
A919_O Inverter Fault – PFC/DSP Comm Fault	15	Drive lost internal communication between PFC and DSP	 Hard Reset of Drive If fault persists - replace drive	Red 9 Flashes
A920_O Inverter Fault – COM/DSP Comm Fault	15	Drive lost internal communication between PFC and DSP	Hard Reset of Drive If fault persists - replace drive	Red 8 Flashes
A921_O Inverter Fault – PFC Temp Sensor Open	15	Sensor to PFC Is either low or open	 Verify proper airflow over the heatsink of the drive. Remove any obstructions. If the problem still persists after a hard reset of the drive, replace the drive. 	Red 1 Flash

EcoNet and Flash Codes

T922_O Inverter Fault – PIM Temp Foldback	15	Drive has folded back as a result of PFC temperature	 Verify proper airflow over the heatsink of the drive. Remove any obstructions. Ensure OD fan is operating and coil is clean Check OD unit clearances. 	Yellow 21 Flashes
T923_O High Refrigerant Pressure	L 29	System High pressure switch has opened.	 Check Refrigerant Charge Check connection of HPS to Drive Check fan at condenser Verify unit clearances 	Yellow 20 Flashes
A923_O High Refrigerant Pressure	L 29	• System High pressure switch has opened 3 times and is locked out for one hour	 Check Refrigerant Charge Check connection of HPS to Drive Check fan at condenser Verify unit clearances 	Yellow 20 Flashes
A925_O Inverter Fault – Compressor Model Unkown	15	Drive size and model data card do not match	Incorrect Memory Card has been installed Incorrect Inverter Drive has been installed	Yellow 22 Flashes
A927_O Inverter Fault – DLT sensor Open	15	• Discharge Line Temperature Sensor is open	Check DLT sensor connection to driveCheck DLT sensor resistance to temp	Red 3 Flashes
A928_O Locked	15	This is an indication that the system is locked out and needs to be reset	Check fault history for cause of lockout condition at control center Address fault as indicated in history	

EcoNet and Flash Codes

A929_O 240VAC Missing or Comm Failure (Formerly Comm Failure)	15	Drive is either not powered or there is a problem with the mod bus cable between VSODU and Drive	 Verify Line voltage to unit is on and is measured by reading line voltage into drive at L1-L2 (Black to Yellow in bottom left corner of drive) Check Modbus cable between VSODU and Drive. Closely Examine pins in connectors. Is choke connected or open? Hard Reset of Drive 	Red 11 Flashes
A950_O Configuration Data Restore Failure		Firmware in VSODU is corrupt	Replace VSODU	
A951_O Memory Card Data Write Failure	d I	VSODU is unable to write data to memory card	 Possible Damage to solder joints on back of memory card socket on VSODU Replace VSODU Replace Memory Card also if VSODU does not resolve. 	
T952_O Outside Temperature Thermistor Failure	84	Outdoor Temperature Thermistor is either Open, Shorted or Low	 Check connection at VSODU Verify leads to sensor are not pinched, or damaged Check sensor resistance/temp 	
A953_O Coil Temperature Thermistor Failure (Formerly called Evap Temperature Thermistor)	83	 Coil Temperature Thermistor is either Open, Shorted or Low Unit will run in cooling mode, but will resort to time/temperature defrost in heating mode 	 Check connection at VSODU Verify leads to sensor are not pinched, or damaged Check sensor resistance/temp 	

EcoNet and Flash Codes

A954_O Suction Temperature Thermistor Failure	35	 Suction Thermistor is either Open, Shorted, or Low Unit will run in cooling mode but will not run in heating mode 	 Check connection at VSODU Verify leads to sensor are not pinched, or damaged Check sensor resistance/temp 	
T955_O Compressor Temperature Thermistor Failure	42	 Sump Thermistor is either Open, Shorted, or Low Stator heat will not operate 	 Check connection at VSODU Verify leads to sensor are not pinched, or damaged Check sensor resistance/temp 	
A956_O Suction Pressure Sensor Failure	36	Suction Transducer is either, shorted, grounded or open or outside of acceptable range	 Check Transducer using formula PSIA= 375*(DCVout/DCVin)-22.8 PSIG=PSIA-14.7 Verify Connections at VSODU and Transducer 	
T957_O Low Refrigerant Pressure	L 21	 Pressure at Transducer has fallen below settings. 50 PSIG for Cooling and 15 PSIG for Heating modes 	 Check Refrigerant Charge Check for Restrictions in liquid or suction lines, drier, strainers etc. Check airflow and load at evaporator 	
A957_O Low Refrigerant Pressure	L 21	 System has tripped the low pressure threshold 3 times in one call. Unit will be locked out for one hour 	 Check Refrigerant Charge Check for Restrictions in liquid or suction lines, drier, strainers etc. Check airflow and load at evaporator 	

EcoNet and Flash Codes

T959_O Compressor Heater On (Normal Operation)	Flashing • Indicated only at control center	 Often times this is a result of short cycling due to envelope protection or pressure switch trips. Usually related to overcharge conditions Compressor Sensor not in correct location or not making good surface contact with compressor. Only Occurs on Firmware version 42 and Earlier. – Install new VSODU 	
T960_O Compressor Lube Protection	Compressor Temperature fell below saturated refrigerant temperature indicating liquid is returning to compressor.	 Check refrigerant charge Can happen in extreme cold temperatures when compressor slows down from overdrive Verify sump sensor is firmly mounted on compressor Compressor speed will fold back or be limited unit sump temperature is 10 degrees above saturated suction temperature. 	
T961_O Compressor Discharge Temperature High	Folding back due to high discharge temperature	 When Discharge temperature exceeds 225°F, Compressor will slow down to bring discharge temperature down below 200°F. Check system superheat and charge Verify reversing valve is not leaking from discharge to suction. 	

EcoNet and Flash Codes

Inverter Product

A962_O or A970_O Inverter/Compressor Mismatch	15	Memory card does not match the compressor and drive installed in the equipment	Likely an incorrect component such as a drive was installed in unit. Check current parts list to make sure correct drive is used.	
---	----	--	--	--

<u>Troubleshooting Notes:</u>

If reversing valve will not shift to heating mode, check fuse on VSODU in addition to solenoid and wiring to reversing valve.

If compressor RPM's are not as expected, check LED on drive to see if it is folding back as a result of an issue.

Many faults can be attributed to system overcharge. Charge in system is critical.